

Lagenaufbau bearbeiten

Aufbau-Schlüssel:

Interne Beschreibung:

Aufbau		Abstände		Materialbedarf			Klassifizierung	
<input checked="" type="checkbox"/> Daten einbeziehen von Teil: <input type="text" value="R4028"/>								
Art	Mat.	Lage	Nom.	Min.	Max.	v.o.	v.u.	
							_0.000	_1.582
BS	Cu 100%	Top	0.035	0.035	0.035	_0.035	_1.547	
	Prepreg		0.094	0.058	0.130	_0.129	_1.453	
I1	Cu 10%	Sig1	0.035	0.035	0.035	_0.164	_1.418	
	Core		0.110	0.100	0.120	_0.274	_1.308	
I2	Cu 90%	GND1	0.035	0.035	0.035	_0.309	_1.273	
	Prepreg		0.164	0.144	0.184	_0.473	_1.109	
I3	Cu 10%	Sig2	0.035	0.035	0.035	_0.508	_1.074	
	Core		0.152	0.125	0.175	_0.660	_0.922	
I4	Cu 90%	GND2	0.035	0.035	0.035	_0.695	_0.887	
	Prepreg		0.192	0.172	0.212	_0.887	_0.695	
I5	Cu 90%	VCC	0.035	0.035	0.035	_0.922	_0.660	
	Core		0.152	0.125	0.175	_1.074	_0.508	
I6	Cu 10%	Sig3	0.035	0.035	0.035	_1.109	_0.473	
	Prepreg		0.164	0.144	0.184	_1.273	_0.309	
I7	Cu 90%	VCC3	0.035	0.035	0.035	_1.308	_0.274	
	Core		0.110	0.100	0.120	_1.418	_0.164	
I8	Cu 10%	Sig4	0.035	0.035	0.035	_1.453	_0.129	
	Prepreg		0.094	0.058	0.130	_1.547	_0.035	
LS	Cu 100%	Bott	0.035	0.035	0.035	_1.582	_0.000	

QS-Datei: