

Wert	Pos 5	Pos 6	Pos 7	Pos 8
0,0	0	0	0	0
128,0	0	0	0	0x35 (5)
1,0	0	0x41 (A)	0	0
2,0	0x31 (1)	0x34 (4)	0	0
4,0	0x32 (2)	0x38 (8)	0	0
8,0	0x35 (5)	0	0	0
16,0	0x41 (A)	0	0	0
16,1	0x41 (A)	0x31 (1)	0	0
16,2	0x41 (A)	0x32 (2)	0	0
16,4	0x41 (A)	0x34 (4)	0	0
16,8	0x41 (A)	0x38 (8)	0	0
999,9	0	0x46 (F)	0x32 (2)	0x37 (7)
0,1	0	0x31 (1)	0	0
0,2	0	0x32 (2)	0	0
0,3	0	0x33 (3)	0	0
0,4	0	0x34 (4)	0	0
0,5	0	0x35 (5)	0	0
0,6	0	0x36 (6)	0	0
0,7	0	0x37 (7)	0	0
0,8	0	0x38 (8)	0	0
0,9	0	0x39 (9)	0	0
1,0	0	0x41 (A)	0	0
2,0	0x31 (1)	0x34 (4)	0	0
3,0	0x31 (1)	0x45 (E)	0	0
4,0	0x32 (2)	0x38 (8)	0	0
5,0	0x33 (3)	0x32 (2)	0	0
6,0	0x33 (3)	0x43 (C)	0	0
7,0	0x34 (4)	0x36 (6)	0	0
8,0	0x35 (5)	0	0	0
9,0	0x35 (5)	0x41 (A)	0	0
10,0	0x36 (6)	0x34 (4)	0	0